

ecology and environment, inc.

1509 MAIN STREET, DALLAS, TEXAS 75201, TEL. 214-742-6601

International Specialists in the Environment

MRMORANDUM

TO:

Ed Sierra, Region VI RPO

THRU:

K. H. Malone, Jr., FITOM

FROM:

Michael N. Mitchell, FIT Geologist

DATE:

August 29, 1991

TDD: F06-9004-03

PAN: FTX1042XAF

SUBJECT:

On-Site Reconnaissance Inspection

Houston Gas Light Company Houston, Harris County, TX

(TXD981918188)

Attached is the On-Site Reconnaissance Inspection Report of the Houston Gas Light Company site. Per instructions from EPA Superfund Project Officer Lonnie Ross (see attached), the task assignment for this project was modified. The On-Site Reconnaissance Inspection Report replaces the LSI Work Plan and Final Report.

Reviewed by 6H-ES Date

PRELIMINARY REPORT This does not constitute final opinion of EPA

90071887